

Article:	HTL:0228	Color:	White	Tig Welding Gloves	Guantlet style cuff	
Size:	S to 4XL	Leather:	Cowhide		Storage Duration:	upto 2 Years



How to decontaminate your leather glove.

Under no circumstances should leather submerged in water.

1. Prepare a lukewarm water solution using mild detergent.
2. Gently wipe your leather glove with a cloth.
3. In- rder to reduce stiffening, allow the leather glove to dry naturally.

None of the materials or processes used in the manufacture of these products are known to be harmful to the wearer. The gloves and information contained herein are designed to accommodate the basic safety requirements and standards for Personal Protective Equipment. Actual conditions of use cannot be directly simulated in a test environment, therefore it is the responsibility of the user and not the manufacturer or supplier to determine the suitability for intended use.



Packaging, Storage & Obsolescence

WELD - Packed 12 pairs per bundle and 60 pairs per carton for shipping. Store in a cool, dry place. Stored correctly, the gloves physical properties will not change for up to two years.

